



SERVICE LETTER NO. 001
September 15, 2023

Subject: Possible mismarking of bezel on Fuel Valve Part Number SHA200F202-120 Fuel Selector Valve LEFT/RIGHT/OFF.

Affected Serial Numbers: 61039, 61040, 61041, 61042

Description: The fuel bezel may have been mismarked with “LIFT OFF” instead of “LIFT KNOB” during manufacture.

1. Sierra Hotel Aero, Inc. recommends during the next pre-flight inspection that the bezel markings be inspected to determine if it shows “LIFT KNOB” as shown in Figure 1. If the bezel is marked correctly no further action is required.
2. If the bezel is marked “LIFT OFF” as shown in Figure 2, contact Sierra Hotel Aero, Inc. at info@navion.com or 651-306-1456, for a temporary decal that can be installed until a replacement bezel is received. The temporary decal can be installed by the owner/operator as depicted in Figure 3.
3. Upon receipt of the correct bezel or at the next maintenance event, have an A&P mechanic replace the bezel and make an entry in the logbook stating the correct bezel PN SHA 200F202-120-101 has been installed.



Figure 1 CORRECT



Figure 2 INCORRECT

Contact information:

Sierra Hotel Aero, Inc.
1690 Aeronca Lane
South St. Paul, MN 55075
651-306-1456 phone
info@navion.com




Figure 3 - Decal Installation and Dimensions as shown.